

Preliminary Report of Accident



1. Accident Type: Fatal Injury		2. Accident Classification Other Accident (Drowning)		3. Date/Time of Accident 12/10/2013 02:45 AM		4. Date/Time of Death		5. Fatal Case No 22							
6. Mine Information :															
a) Mining Company Name Hunter Sand & Gravel LLC.			b) Mine Name Dredge IV			c) Parent of Mining Company HMT Holdings, Inc.									
7. Mine Location :		a) City Ledbetter		b) County Livingston		c) State KY		8. Mine ID Number: 15-17687		9. Union: NO					
10. Primary Mineral Mined: COMMON SAND MINING			11. Number of Mine Employees:		a) Total 10		b) Underground 0		c) Open Pit/Quarry 0		d) Mill/Prep Plant 0		e) Other 10		
12. Contractor Name:							13. Union		14. Contractor ID Number:						
15. Contractor Address:		a) City		b) County		c) State		d) Zip Code							
16. Number of Contractor Employees:		a) Total		b) Underground		c) Open Pit/Quarry		d) Mill/Prep Plant		e) Other					
17. Number of Persons in Mine at Time of Accident:						18. Number of Persons Unaccounted For:									
a) Mine Employees: 5		b) Contractor Employees:				a) Mine Employees: 1		b) Contractor Employees:							
19) Location of Accident										20. Mining Height:					
<input type="checkbox"/> 01-Underground		<input type="checkbox"/> 03-Open Pit		<input type="checkbox"/> 07-Advance Mining		<input type="checkbox"/> 30-Mill/Prep Plant		<input type="checkbox"/> Other (specify)		Feet Inches					
<input type="checkbox"/> 02-Surface at Underground		<input checked="" type="checkbox"/> 06-Dredge Mining		<input type="checkbox"/> 08-Retreat Mining		<input type="checkbox"/> 99-Office Facility									
21. Nonfatal Injuries:			22. Fatal Injuries: 1												
23. Victim Information :		a) Name Dustin Burnham			b) Age 27										
c) Regular Job Title: Deckhand		d) Activity at Time of Accident: Deckhand			<input checked="" type="checkbox"/> Mine Employee										
24. Experience :		Years Weeks Days		Years Weeks Days		Years Weeks Days		Years Weeks Days							
a) Total:		4 37 0		b) at the mine:		0 6 4		c) at activity (23d)		4 37 0		d) with Contractor		0 0 0	
25. Autopsy Performed: If Yes, Location							26. Mine Telephone No.: (270) 898-8613								

27. Description of Accident (include equipment involved, the exact location in the mine, and status of rescue and recovery operations):

The miner was working on a dredge that had a barge tied to its right front side. The victim stepped on the barge to observe the level indicators when he fell into the water.

The information provided in this notice is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the accident.

28. Equipment Manufacturer:				29. Model:			
30. District: M3000 Southeastern		32. Field Office: Franklin TN				33. Event Number: 6643374	
34. Accident Investigator: Scott Jomson		35. MSHA Person Notified: Michael A. Evans		Date 12/10/2013		Time 04:42 A	
36. Type of Report: Amended		37. Name of Preparer and Date Prepared: Mike Harcher <i>mj</i>				Date 12/16/2013	
38. Reason For Amendment: Item 24 a, b, c							